




Fokker 50 Leading Edge Repair



Both De Icer Boot types (Non FASTboot & FASTboot) can be replaced. FASTboots are the new de icer boot generation with improved technology and reliability.

Flat Rate Exchange Units are available.

1	Center wing leading edge LH	F4100-260-xxx
2	Center wing leading edge RH	F4100-260-xxx
3	Outer wing leading edge no 1 LH	F4100-275-xxx
4	Outer wing leading edge no 1 RH	F4100-275-xxx
5	Outer wing leading edge no 2 LH	F4100-276-xxx
6	Outer wing leading edge no 2 RH	F4100-276-xxx
7	Outer wing leading edge no 3 LH	F4100-277-xxx
8	Outer wing leading edge no 3 RH	F4100-277-xxx
9	Outer wing leading edge no 4 LH	F4100-278-xxx
10	Outer wing leading edge no 4 RH	F4100-278-xxx
11	Inboard Horizontal Stabilizer Leading Edge LH	F4100-230-xxx
12	Inboard Horizontal Stabilizer Leading Edge RH	F4100-230-xxx
13	Outboard Horizontal Stabilizer Leading Edge LH	F4100-231-xxx
14	Outboard Horizontal Stabilizer Leading Edge LH	F4100-231-xxx
15	Vertical Stabilizer Leading Edge	F4100-245-xxx

Head Office:

MSI

Pommernstrasse 8
65428 Ruesselsheim
Germany

Tel. (49) 6142 955 115
Fax (49) 6142 955 111

MSI

Flughafenallee 15
28199 Bremen
Germany

Tel. (49) 421 557 1913
Fax (49) 421 557 1930

Middle East Office

MSI

PO Box 17462
Jebel Ali, FZS1 BH02
Dubai, UAE

Tel. (971) 4 886 1122
Fax (971) 4 886 1121